

Oil Field Environmental Incident Summary

Incident: 20140625085907

Date/Time of Notice: 06/25/2014 08:59

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: MARGARET ELIZABETH 4-33H

Field Name: MCGREGOR

Well File #: 20198

Date Incident: 3/12/2014

Time Incident: 07:30

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 95

Sec: 4

Qtr: SW SE

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	60	Barrels	60	Barrels	60	barrels
Brine	25	Barrels	25	Barrels	25	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/30/2014

Clean Up Concluded: 6/26/2014

Risk Evaluation:

None

Areal Extent:

small area of pooled oil on the edge of site and misting oil on snow and ice in adjacent field.

Potential Environmental Impacts:

None

Action Taken or Planned:

Closer inspection of treater burner gaskets

Wastes Disposal Location: Brine and oil placed in production tank for recycling. Sorbents removed for disposal.

Agencies Involved:

Updates

Date: 6/25/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release of oil and production water pooled partly on location and sprayed off location. Followup is necessary to determine whether adequate cleanup was completed and why report was not submitted at time of release.

Date: 7/1/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

7/1/14 - 14:35 on location. Treater leak listed as cause of the March 12 release that was just reported on June 25. Treater is in NW corner of the location; flare pit is in the NE. Examined ground inside the treater dike and noticed two small areas of oil scum floating on recent rain water. Went to NW corner of locaion and took photos of area and surrounding field. Do not see any obvious impact scars from the release. Took photos with embedded GPS.